REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	4/12/2021	**Time:** 10:26 AM
Name of School Corporation:	CARMEL CLAY SCHOOLS				**Corp ID:** 293060
Address of School Corporation:	5185 E 131st St				
City:	Carmel	**Zip:**	46032		**County Number:** 29
VIN:	4DRBWAARXEB774306		**License Number:**	6185	**Bus Number:** 40
Make of Body:	IC Corporation	**Year:** 2013	**Make of Chassis:**	IC Corporation	**Year:** 2014
Bus Type:	D		**Mileage:**	70677	
Inspection Status:	O	**Inspected By:**	Jeff Stone		**PE:** 8184

Violations - Rejected

Inspection Code	Description
64-1-4	Any front turn signal does not function properly
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.