

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/13/2021	Time:	9:08 AM
Name of School Corporation:	PRIMROSE SCHOOL @ WEST CLAY	Corp ID:	46032		
Address of School Corporation:	13096 Moultrie St.				
City:	Carmel	Zip:	46032	County Number:	29
VIN:	1GBHG31C381231865	License Number:	PRB3	Bus Number:	J2
Make of Body:	Collins Bus Corporation	Year:	2008	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	49505	Year:	2008
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
61-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.