

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	4/14/2021	<b>Time:</b>	9:52 AM
<b>Name of School Corporation:</b>	PRIMROSE SCHOOL @ WEST CLAY			<b>Corp ID:</b>	46032
<b>Address of School Corporation:</b>	13096 Moultrie St.				
<b>City:</b>	Carmel	<b>Zip:</b>	46032	<b>County Number:</b>	29
<b>VIN:</b>	1GBHG31C381231865	<b>License Number:</b>	PRB3	<b>Bus Number:</b>	J2
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2008	<b>Mileage:</b>	49505	<b>PE:</b>	8184
<b>Bus Type:</b>	A2	<b>Inspected By:</b>	Jeff Stone		
<b>Inspection Status:</b>	O				

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.