# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 4/14/2021 | **Time:** | 10:24 AM |
| **Name of School Corporation:** | PRIMROSE SCHOOL OF CARMEL | | | **Corp ID:** | 290005 |
| **Address of School Corporation:** | 780 W. Carmel Dr. | | | | |
| **City:** | Carmel | **Zip:** | 46032 | **County Number:** | 29 |
| **VIN:** | 1GBHG31C091111801 | **License Number:** | B490C | **Bus Number:** | 1 |
| **Make of Body:** | Chevrolet **Year:** 2009 | **Make of Chassis:** | Chevrolet | **Year:** | 2009 |
| **Bus Type:** | A1 | **Mileage:** | 18200 | | |
| **Inspection Status:** | O | **Inspected By:** | Jeff Kastenschmidt | **PE:** | 5805 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 57-1-5 | Step-well light is missing or inoperative |
| 43-1-8 | Any required lettering is missing or faded. |
| 70-1-1 | There is unapproved glazing material installed in the bus |
| 70-1-8 | Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 8-2-5 | There is brake fluid leaking at any point |
| 50-2-1 | There is no seat belt cutter in the vehicle |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**