

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|--------------|-------------------------|-----------------------|
| Type of Inspection: | Annual | Date: | 4/15/2021 | Time: | 9:38 AM |
| Name of School Corporation: | MARION COMMUNITY SCHOOLS | | | Corp ID: | 272865 |
| Address of School Corporation: | 826 E 30th St | | | | |
| City: | Marion | Zip: | 46952 | County Number: | 27 |
| VIN: | 1BAKJCPA2AF274475 | License Number: | 74384 | Bus Number: | 15 |
| Make of Body: | Blue Bird Corporation | Year: | 2009 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | C | Mileage: | 127476 | Year: | 2010 |
| Inspection Status: | R | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |
| 44-1-1 | Any marker light or lens is missing, cracked, faded, wrong color, or inoperative |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.