REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/15/2021	**Time:**	10:34 AM
Name of School Corporation:	TRI-COUNTY SCHOOL CORPORATION			**Corp ID:**	918535
Address of School Corporation:					
City:		**Zip:**		**County Number:**	91
VIN:	1HVBBAANX4H673706	**License Number:**	9387	**Bus Number:**	15
Make of Body:	Blue Bird Corporation **Year:** 2004	**Make of Chassis:**	IC Corporation	**Year:**	2004
Bus Type:		**Mileage:**	157108		
Inspection Status:	O	**Inspected By:**	Nate King	**PE:**	7421

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
18-2-3	Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)

Bus Type Description