

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 4/20/2021 **Time:** 10:02 AM
Name of School Corporation: EDINBURGH COMM. SCHOOL CORP. **Corp ID:** 414215
Address of School Corporation: 202 S Keeley St
City: Edinburg **Zip:** 46124 **County Number:** 41
VIN: 4DRBWAAR0CB392363 **License Number:** 15526 **Bus Number:** 7
Make of Body: IC Corporation **Year:** 2010 **Make of Chassis:** IC Corporation **Year:** 2012
Bus Type: D **Mileage:** 72059
Inspection Status: O **Inspected By:** Jeff Kastenschmidt **PE:** 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
70-1-7	Any emergency window is too difficult to open
7-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.