

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 4/23/2021 **Time:** 8:25 AM  
**Name of School Corporation:** HANOVER COMM. SCHOOL CORP. **Corp ID:** 454580  
**Address of School Corporation:** PO Box 645  
**City:** Cedar Lake **Zip:** 46303 **County Number:** 45  
**VIN:** 1GB3G2BG1C1196659 **License Number:** 14188 **Bus Number:** 44  
**Make of Body:** Star Trans **Year:** 2012 **Make of Chassis:** Chevrolet **Year:** 2012  
**Bus Type:** **Mileage:** 72546  
**Inspection Status:** R **Inspected By:** Tim Grayson **PE:** 7558

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description