REPORT OF SCHOOL BUS INSPECTION

Type of 9:46 Time: Annual Date: 4/20/2021 Inspection: AM Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS Corp ID: 475075 **Address of School Corporation:** 595 Stars Blvd County City: Bedford Zip: 47421 47 Number: License VIN: 1HVBBABN0XH260261 17040 **Bus Number:** A21 Number: Make of IC Blue Bird **Year:** 1996 Make of Body: Year: 2000 Corporation Corporation Chassis: **Bus Type:** С Mileage: 243675 Inspected PE: 5892 **Inspection Status:** O Travis Coryea By:

Violations - Rejected

Inspection Code Description

70-1-7 Any emergency window is too difficult to open

29-1-2 Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.