

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------------|------------------------|-------------|-------------------------|-------------------------|--------------|------|
| Type of Inspection: | Annual | Date: | 4/26/2021 | Time: | 11:20 AM | | |
| Name of School Corporation: | LEBANON COMMUNITY SCHOOL CORP. | | | Corp ID: | 60665 | | |
| Address of School Corporation: | 505 Ransdell Rd | | | | | | |
| City: | Lebanon | Zip: | 46052 | County Number: | 6 | | |
| VIN: | 1GB3GRBG8H1349487 | License Number: | 56986 | Bus Number: | 106 | | |
| Make of Body: | Chevrolet | Year: | 2018 | Make of Chassis: | Collins Bus Corporation | Year: | 2017 |
| Bus Type: | B | Mileage: | 23531 | | | | |
| Inspection Status: | A | Inspected By: | Rob Hawkins | PE: | 5199 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.