

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 4/28/2021 **Time:** 9:02 AM
Name of School Corporation: BARTHOLOMEW CONS. SCHOOL CORP. **Corp ID:** 30365
Address of School Corporation: 1260 N Marr Rd
City: Columbus **Zip:** 47201 **County Number:** 3
VIN: 1GB3G2BG5F1138736 **License Number:** 34017 **Bus Number:** W13
Make of Body: Chevrolet **Year:** 2015 **Make of Chassis:** Chevrolet **Year:** 2015
Bus Type: **Mileage:** 91559
Inspection Status: R **Inspected By:** Travis Coryea **PE:** 5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

Inspection Code Description

Bus Type Description