REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/29/2021	**Time:**	10:47 AM
Name of School Corporation:	CREATIVE CAMPUS CHILD CARE			**Corp ID:**	290020
Address of School Corporation:	19043 Cumberland Rd.				
City:	Noblesville	**Zip:**	46060	**County Number:**	29
VIN:	1GBHG31V961133180	**License Number:**	B117F	**Bus Number:**	1
Make of Body:	Chevrolet **Year:** 2006	**Make of Chassis:**	Chevrolet	**Year:**	2006
Bus Type:	A1	**Mileage:**	78494		
Inspection Status:	O	**Inspected By:**	Rob Hawkins	**PE:**	5199

Violations - Rejected

Inspection Code	Description
50-1-2	The seat belt cutter is not secured using a positive fastening method.
61-1-5	See Notes: Any defect inspector deems a violation not listed
22-1-1	A dripping oil or fluid leak
41-1-8	The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**