

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/29/2021 Time: 10:47 AM
Name of School Corporation: CREATIVE CAMPUS CHILD CARE Corp ID: 290020
Address of School Corporation: 19043 Cumberland Rd.
City: Noblesville Zip: 46060 County Number: 29
VIN: 1GBHG31V961133180 License Number: B117F Bus Number: 1
Make of Body: Chevrolet Year: 2006 Make of Chassis: Chevrolet Year: 2006
Bus Type: A1 Mileage: 78494
Inspection Status: O Inspected By: Rob Hawkins PE: 5199

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |
| 61-1-5 | See Notes: Any defect inspector deems a violation not listed |
| 22-1-1 | A dripping oil or fluid leak |
| 41-1-8 | The interior storage container (MFSAB/Special Purpose Bus ONLY) is not securely fastened to the floor or does not have a cover with a positive fastening device. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.