REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	5/4/2021	**Time:**	9:23 AM
Name of School Corporation:		UNION SCHOOL CORPORATION				**Corp ID:**	686795
Address of School Corporation:		8707 W US 36					
City:	Modoc	**Zip:**	47358			**County Number:**	68
VIN:	4drbuskp1bb262051			**License Number:**	7134	**Bus Number:**	5
Make of Body:	IC Corporation	**Year:**	2009	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	C			**Mileage:**	95747		
Inspection Status:	O	**Inspected By:**		Jamie Hotchkiss		**PE:**	6458

Violations - Rejected

Inspection Code	Description
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.