REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/4/2021	**Time:**	9:44 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	1HVBBABP7YH307899	**License Number:**	17633	**Bus Number:**	4
Make of Body:	Blue Bird Corporation **Year:** 2000	**Make of Chassis:**	IC Corporation	**Year:**	2001
Bus Type:	C	**Mileage:**	87841		
Inspection Status:	O	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
62-1-2	One (1) taillight or one (1) brake light does not function
2-1-1	Required back-up lights do not function.

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.