REPORT OF SCHOOL BUS INSPECTION

Type of 9:44 Time: Annual Date: 5/4/2021 Inspection: AM UNION SCHOOL CORPORATION 686795 Name of School Corporation: Corp ID: **Address of School Corporation:** 8707 W US 36 County City: Modoc Zip: 47358 68 Number: License VIN: 1HVBBABP7YH307899 17633 **Bus Number:** 4 Number: Make of IC Blue Bird Year: 2000 Make of Body: Year: 2001 Corporation Corporation Chassis: **Bus Type:** С Mileage: 87841 Inspected PE: **Inspection Status:** O Jamie Hotchkiss 6458 By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

One (1) taillight or one (1) brake light does not function

2-1-1 Required back-up lights do not function.

Violations - Out of Service

<u>Inspection</u>	Description
Code	<u>Description</u>

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.