

## REPORT OF SCHOOL BUS INSPECTION

|  |                                    |                                 |
|--|------------------------------------|---------------------------------|
| <b>Type of Inspection:</b> Annual                        | <b>Date:</b> 5/11/2021             | <b>Time:</b> 10:56 AM           |
| <b>Name of School Corporation:</b> MARQUETTE HIGH SCHOOL | <b>Corp ID:</b> 71002Z             |                                 |
| <b>Address of School Corporation:</b> 306 W 10th St.     |                                    |                                 |
| <b>City:</b> Michigan City                               | <b>Zip:</b> 46306                  | <b>County Number:</b> 46        |
| <b>VIN:</b> 1GBHG31R6Y1201361                            | <b>License Number:</b> b872aa      | <b>Bus Number:</b> 1            |
| <b>Make of Body:</b> Chevrolet                           | <b>Year:</b> 2000                  | <b>Make of Chassis:</b> Corbeil |
| <b>Year:</b> 2000  | <b>Bus Type:</b>                   | <b>Mileage:</b> 133658          |
| <b>Inspection Status:</b> O                              | <b>Inspected By:</b> Nathan Sherer | <b>PE:</b> 7029                 |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 50-2-1                 | There is no seat belt cutter in the vehicle  |
| 8-2-1                  | There is no brake certification, or the certification has expired or is not signed |

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|