

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	5/12/2021	<b>Time:</b>	12:17 PM
<b>Name of School Corporation:</b>	M.S.D. MARTINSVILLE SCHOOLS	<b>Corp ID:</b>	555925		
<b>Address of School Corporation:</b>	PO Box 1416				
<b>City:</b>	Martinsville	<b>Zip:</b>	46151	<b>County Number:</b>	55
<b>VIN:</b>	4UZABRFC6KCKY2405	<b>License Number:</b>	22662	<b>Bus Number:</b>	48
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2019	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	C	<b>Mileage:</b>	18002	<b>Year:</b>	2019
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mark Raper	<b>PE:</b>	6473

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
33-1-2	The grill is missing
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
36-1-1	The latch does not secure the hood tightly
34-1-1	Any headlight is inoperative
22-1-1	A dripping oil or fluid leak

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**