

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/3/2021	<b>Time:</b>	9:21 AM
<b>Name of School Corporation:</b>	MEDORA COMMUNITY SCHOOL CORP.			<b>Corp ID:</b>	363640
<b>Address of School Corporation:</b>	Box 248				
<b>City:</b>	Medora	<b>Zip:</b>	47260	<b>County Number:</b>	36
<b>VIN:</b>	1BAKF CPA4BF274979	<b>License Number:</b>	4413	<b>Bus Number:</b>	2
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	86820	<b>Year:</b>	2010
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Travis Coryea	<b>PE:</b>	5892

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**