

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/13/2021	Time:	9:04 AM
Name of School Corporation:	AVON COMMUNITY SCHOOLS	Corp ID:	323315		
Address of School Corporation:	7203 E HWY 36				
City:	Avon	Zip:	46123	County Number:	32
VIN:	4DRBWAAR29A070774	License Number:	30767	Bus Number:	144
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2009
Bus Type:	D	Mileage:	123218		
Inspection Status:	A	Inspected By:	Joel Flores	PE:	7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.