## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/25/2021Time:9:24 AMName of School Corporation:CRAWFORD CO. COMM. SCHOOL CORPCorp ID:131300

Address of School Corporation: 5808 E Administration Rd

City:MarengoZip:47140County Number:13VIN:4DRBUAAP67B369826License Number:NBCCS51Bus Number:51Make of Body:IC Corporation Year:2007
Make of Chassis: IC Corporation Year:

Bus Type: C Mileage: 136214

Inspection Status: A Inspected By: Mike Adams PE: 7407

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.