

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|-------------------------|
| Type of Inspection: | Annual | Date: | 5/25/2021 | Time: | 10:03 AM |
| Name of School Corporation: | CRAWFORD CO. COMM. SCHOOL CORP | | | Corp ID: | 131300 |
| Address of School Corporation: | 5808 E Administration Rd | | | | |
| City: | Marengo | Zip: | 47140 | County Number: | 13 |
| VIN: | 1GB6G5BG5B1162740 | License Number: | 2625 | Bus Number: | 44 |
| Make of Body: | GMC | Year: | 2011 | Make of Chassis: | Collins Bus Corporation |
| Bus Type: | A2 | Mileage: | 164959 | Year: | 2011 |
| Inspection Status: | O | Inspected By: | Mike Adams | PE: | 7407 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---------------------------------------------------------------------------------------------------|
| 20-2-1 | Is no audible signal when the emergency door is open and ignition switch is on |
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**