

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------------|------------------------|------------|-------------------------|-----------|--------------|------|
| Type of Inspection: | Re-Inspection | Date: | 5/25/2021 | Time: | 10:52 AM | | |
| Name of School Corporation: | CRAWFORD CO. COMM. SCHOOL CORP | | | Corp ID: | 131300 | | |
| Address of School Corporation: | 5808 E Administration Rd | | | | | | |
| City: | Marengo | Zip: | 47140 | County Number: | 13 | | |
| VIN: | 1GB6GUBG9G1305285 | License Number: | 5052 | Bus Number: | 42 | | |
| Make of Body: | Collins Bus Corporation | Year: | 2016 | Make of Chassis: | Chevrolet | Year: | 2016 |
| Bus Type: | A2 | Mileage: | 69120 | | | | |
| Inspection Status: | A | Inspected By: | Mike Adams | PE: | 7407 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.