# **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection:         | Annual                      |       |                    | Date:               | 5/25/2021    | Time:             | 11:57<br>AM |
|--------------------------------|-----------------------------|-------|--------------------|---------------------|--------------|-------------------|-------------|
| Name of School (               | •                           | EAST  |                    | INTY SCHOOLS        |              | Corp ID:          | 20255       |
| Address of School Corporation: |                             |       | 1322 Green Rd      |                     |              |                   |             |
| City:                          | New Haven                   |       | Zip:               | 46774               |              | County<br>Number: | 2           |
| VIN:                           | 4UZABRDT1ECFM5247           |       | License<br>Number: | 7116                | Bus Number:  | 16                |             |
| Make of Body:                  | Thomas Built Buses,<br>Inc. | Year: | 2013               | Make of<br>Chassis: | Freightliner | Year:             | 2014        |
| Bus Type:                      | С                           |       |                    | Mileage:            | 139147       |                   |             |
| Inspection<br>Status:          | 0                           |       | Inspected<br>By:   | Eric Egbert         |              | PE:               | 7006        |

## Violations - Rejected

#### Inspection Code Description

# Violations - Out of Service

Inspection<br/>CodeDescription70-2-4Audible warning device, when required, is not working properly. Buzzers are required<br/>after 5-2-94

# **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.