REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/20/2021	**Time:**	12:53 PM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	**Zip:**	46036	**County Number:**	48
VIN:	4DRBIAAP48B494499	**License Number:**	30363	**Bus Number:**	1
Make of Body:	IC Corporation **Year:** 2006	**Make of Chassis:**	IC Corporation	**Year:**	2006
Bus Type:	C	**Mileage:**	108240		
Inspection Status:	O	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.