REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/27/2021	**Time:**	9:48 AM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			**Corp ID:**	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	**Zip:**	45242	**County Number:**	18
VIN:	1GB3GSBGXH1134782	**License Number:**	B890N	**Bus Number:**	M40
Make of Body:	Chevrolet **Year:** 2017	**Make of Chassis:**	AmTran	**Year:**	2017
Bus Type:	A1	**Mileage:**	36684		
Inspection Status:	R	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**