

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/3/2021	Time: 10:38 AM
Name of School Corporation: NORTHERN WELLS COMM. SCHOOLS	Corp ID: 908435	
Address of School Corporation:		
City:	Zip:	County Number: 90
VIN: 4DRBVAAR25A974766	License Number: 4218	Bus Number: 12
Make of Body: IC Corporation	Make of Chassis: IC Corporation	Year: 2005
Bus Type: D	Mileage: 217313	
Inspection Status: O	Inspected By: Jamie Hotchkiss	PE: 6458

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
24-1-1	The bus body has rust or rusted through areas which may weaken the body

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-2	The tank is not properly secured
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.