REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 6/7/2021 | Time: | 10:05 AM |
|--------------------------------|----------------------------|-------|------------------|---------------------|-----------|-------------------|-------------|
| Name of School (| • | LEW | | OOL CORPORATI | ON | Corp ID: | 90815 |
| Address of School Corporation: | | | 6422 E SR 218 | | | | |
| City: | Walton | | Zip: | 46994 | | County Number: | 9 |
| VIN: | 1GB6G3A6XA1117272 | 2 | | License Number: | 83787 | Bus Number: | 10 |
| Make of Body: | Collins Bus Corporation | Year: | : 2010 | Make of Chassis: | Chevrolet | Year: | 2010 |
| Bus Type: | A2 | | | Mileage: | 91266 | | |
| Inspection Status | :: 0 | | Inspected By: | Randy McPike | | PE: | 7018 |

Violations - Rejected

| Inspection Code | Description |
|-----------------|--|
| 68-1-1 | Washers do not function properly in any manner |

Violations - Out of Service

| Inspection Code | Description |
|--------------------|---|
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.