

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/10/2021	Time:	9:22 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	1BAKFCPH4AF271303		License Number:	72274	Bus Number:	1	
Make of Body:	Blue Bird Corporation	Year:	2010	Make of Chassis:	Blue Bird Corporation	Year:	2010
Bus Type:	C			Mileage:	110292		
Inspection Status:	O	Inspected By:	Nate King	PE:	7421		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
51-1-1	Any door seals are missing, damaged, or torn

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.