

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	6/10/2021	Time:	10:36 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.	Corp ID:	80750				
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	4DRBUC8P5HB722463	License Number:	12553	Bus Number:	22		
Make of Body:	IC Corporation	Year:	2017	Make of Chassis:	IC Corporation	Year:	2017
Bus Type:	C	Mileage:	44656				
Inspection Status:	O	Inspected By:	Nate King	PE:	7421		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
17-1-1	Any dome light is inoperative
52-1-2	Any shock absorber is leaking fluid

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.