

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 6/10/2021 **Time:** 10:50 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750
Address of School Corporation: 2 S 3rd St.
City: Flora **Zip:** 46929 **County Number:** 8
VIN: 4DRBUAAPXBB334280 **License Number:** 75018 **Bus Number:** 24
Make of Body: IC Corporation **Year:** 2011 **Make of Chassis:** IC Corporation **Year:** 2011
Bus Type: C **Mileage:** 105163
Inspection Status: O **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
2-1-4	LED type lights have 25% or more of the pixels inoperable in any one light
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.