

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/10/2021	Time:	11:20 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	4DRBUSKN8EB765918	License Number:	6222	Bus Number:	18		
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	D	Mileage:	90771	PE:	7421		
Inspection Status:	O	Inspected By:	Nate King				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
22-1-1	A dripping oil or fluid leak
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.