

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 6/10/2021 **Time:** 11:35 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750
Address of School Corporation: 2 S 3rd St.
City: Flora **Zip:** 46929 **County Number:** 8
VIN: 4DRBUC8P4MB864961 **License Number:** 23665 **Bus Number:** 16
Make of Body: IC Corporation **Year:** 2019 **Make of Chassis:** IC Corporation **Year:** 2021
Bus Type: C **Mileage:** 23584
Inspection Status: O **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-2	Any shock absorber is leaking fluid

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.