## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/10/2021 Time:12:16 PMName of School Corporation: CARROLL CONS. SCHOOL CORP.Corp ID:80750

Address of School Corporation: 2 S 3rd St.

City:FloraZip:46929County Number:8VIN:1GB3G2BL6D1167608License Number:19265Bus Number:3sbMake of Body:Chevrolet Year:2013Make of Chassis:Chevrolet Year:2013

Bus Type: A1 Mileage: 118655

Inspection Status: O Inspected By: Nate King PE: 7421

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

22-1-1 A dripping oil or fluid leak

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.