

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/10/2021	Time:	12:32 PM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	1GB3GSBL9G1324634	License Number:	48588	Bus Number:	2sb		
Make of Body:	Chevrolet	Year:	2016	Make of Chassis:	Collins Bus Corporation	Year:	2016
Bus Type:	C	Mileage:	60443				
Inspection Status:	O	Inspected By:	Nate King	PE:	7421		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.