## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 6/10/2021 Time: 12:40 PM

Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City: Flora Zip: 46929 County 8 Number:

Make of Body: Collins Bus Corporation Year: 2012 Make of Chassis: Chevrolet Year: 2012

Bus Type: Mileage: 122527

Inspection Status: O Inspected By: Nate King PE: 7421

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

22-1-1 A dripping oil or fluid leak

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**