REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	5/21/2021	**Time:**	1:15 PM
Name of School Corporation:		NORTH PUTNAM COMMUNITY SCHOOLS				**Corp ID:**	676715
Address of School Corporation:		Box 169					
City:	Bainbridge	**Zip:**	46105			**County Number:**	67
VIN:	1GB3GSBG8K1174334			**License Number:**	24043	**Bus Number:**	421
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2019	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2021
Bus Type:				**Mileage:**	16393		
Inspection Status:	O	**Inspected By:**		Byron Goodman		**PE:**	7008

Violations - Rejected

Inspection Code	Description
95-1-10	Does not move smoothly or rest solidly on the ground
95-1-1	The lifting mechanism does not lift a minimum load of eight hundred (800) pounds
95-1-9	Cannot mechanically lock lift in the upright position by means other than a support or lug on the door
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description

Bus Type Description