

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 5/21/2021 **Time:** 2:40 PM
Name of School Corporation: CLAY COMMUNITY SCHOOLS **Corp ID:** 111125
Address of School Corporation: PO Box 169
City: Knightsville **Zip:** 47857 **County Number:** 11
VIN: 1GB3G2BG3F1115035 **License Number:** 32404 **Bus Number:** 74
Make of Body: Chevrolet **Year:** 2014 **Make of Chassis:** Starcraft **Year:** 2015
Bus Type: A2 **Mileage:** 52972
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
51-1-1	Any door seals are missing, damaged, or torn

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
51-2-1	The service door does not open or close properly

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.