

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/14/2021	Time:	9:37 AM
Name of School Corporation:	NORTHWESTERN SCHOOL CORP.			Corp ID:	343470
Address of School Corporation:	3075 N Washington St				
City:	Kokomo	Zip:	46901	County Number:	34
VIN:	4DRBUC8N2GB726032			License Number:	B549D
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation
Bus Type:	C			Year:	2016
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
59-1-9	There is air leak at the stop arm air bladder that does not affect the air braking system
7-1-2	ABS warning light is illuminated
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
57-1-5	Step-well light is missing or inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.