REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	6/21/2021	**Time:**	11:11 AM
Name of School Corporation:	HERITAGE CHRISTIAN SCHOOL			**Corp ID:**	49C275
Address of School Corporation:	6401 E 75th St				
City:	Indianapolis	**Zip:**	46250	**County Number:**	49
VIN:	4DRBUSKN3BB262258	**License Number:**	B292R	**Bus Number:**	18
Make of Body:	IC Corporation **Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	D	**Mileage:**	105675		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.