REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	6/21/2021	**Time:**	3:15 PM
Name of School Corporation:	CENTERVILLE-ABINGTON COMM SCHS				**Corp ID:**	898360
Address of School Corporation:	116 W SOUTH ST					
City:	CENTERVILLE	**Zip:**	47330		**County Number:**	89
VIN:	4DRBUC8N4JB568476		**License Number:**	15397	**Bus Number:**	M6
Make of Body:	IC Corporation	**Year:** 2017	**Make of Chassis:**	IC Corporation	**Year:**	2017
Bus Type:	C		**Mileage:**	57468		
Inspection Status:	O	**Inspected By:**	Jeremy Mason		**PE:**	8139

Violations - Rejected

Inspection Code	Description
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.