

# REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection **Date:** 6/22/2021 **Time:** 10:12 AM  
**Name of School Corporation:** OLD NATIONAL TRAIL SPECIAL SERVICES **Corp ID:** 530001  
**Address of School Corporation:**  
**City:** **Zip:** **County Number:** 67  
**VIN:** 1GB3G3BG2B1151962 **License Number:** 9454 **Bus Number:** 2  
**Make of Body:** Collins Bus Corporation **Year:** 2011 **Make of Chassis:** Chevrolet **Year:** 2011  
**Bus Type:** **Mileage:** 22217  
**Inspection Status:** R **Inspected By:** Byron Goodman **PE:** 7008

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-10	The exhaust system is not properly installed
23-1-9	Tailpipe has been reduced in a size (diameter) from the rear of the muffler
23-1-11	Any tailpipe exits beneath an emergency door

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------