REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	7/13/2021	**Time:**	10:09 AM
Name of School Corporation:		LAPORTE COMMUNITY SCHOOL CORP.				**Corp ID:**	464945
Address of School Corporation:		1921 A St					
City:	La Porte	**Zip:**	46350			**County Number:**	46
VIN:	4DRBUAAN3FB517752			**License Number:**	7207	**Bus Number:**	55
Make of Body:	IC Corporation	**Year:**	2014	**Make of Chassis:**	IC Corporation	**Year:**	2015
Bus Type:	C			**Mileage:**	39982		
Inspection Status:	O	**Inspected By:**	Tim Grayson			**PE:**	7558

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.