REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		Date:	7/15/2021	Time:	9:46 AM
Name of School Co	orporation: SOU	TH DEARBORN	COMM. SCH. COI	RP	Corp ID:	151600
Address of School Corporation: 6109 Squ		6109 Squire Pl	ace			
City:	Aurora	Zip:	47001		County Number:	15
VIN:	4UZAAXCS07CV	V45100	License Number:	B751H	Bus Number:	14
Make of Body:	Freightliner Year	2006	Make of Chassis:	Freightliner	Year:	2007
Bus Type:	С		Mileage:	137124		
Inspection Status:	R	Inspected By:	Chris Clark		PE:	6665

Violations - Rejected

Inspection CodeDescription43-1-8Any required lettering is missing or faded.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.