REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/19/2021	**Time:**	11:35 AM
Name of School Corporation:	LAKE CENTRAL SCHOOL CORP.			**Corp ID:**	454615
Address of School Corporation:	8855 Wicker Ave				
City:	St John	**Zip:**	46373	**County Number:**	45
VIN:	4DRBUSKN3EB418352	**License Number:**	5727	**Bus Number:**	75
Make of Body:	IC Corporation **Year:** 2012	**Make of Chassis:**	IC Corporation	**Year:**	2014
Bus Type:	C	**Mileage:**	103940		
Inspection Status:	R	**Inspected By:**	Nathan Sherer	**PE:**	7029

Violations - Rejected

Inspection Code	Description
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.