

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 7/21/2021 **Time:** 9:41 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750
Address of School Corporation: 2 S 3rd St.
City: Flora **Zip:** 46929 **County Number:** 8
VIN: 1GB3G2BL3E1174467 **License Number:** 26781 **Bus Number:** 5sb
Make of Body: Starcraft **Year:** 2014 **Make of Chassis:** Starcraft **Year:** 2014
Bus Type: **Mileage:** 71916
Inspection Status: A **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description