## REPORT OF SCHOOL BUS INSPECTION

| Type of<br>Inspection:         | Annual                      |                               |                  | Date:               | 8/4/2021     | Time:             | 11:28<br>AM |
|--------------------------------|-----------------------------|-------------------------------|------------------|---------------------|--------------|-------------------|-------------|
| Name of School Corporation:    |                             | BROWNSBURG COMM. SCHOOL CORP. |                  |                     | Corp ID:     | 323305            |             |
| Address of School Corporation: |                             | 310 Stadium Drive             |                  |                     |              |                   |             |
| City:                          | Brownsburg                  |                               | Zip:             | 46112               |              | County<br>Number: | 32          |
| VIN:                           | 4UZABRFC8MCMF83             | 19                            |                  | License<br>Number:  | 23929        | Bus Number:       | 70          |
| Make of Body:                  | Thomas Built Buses,<br>Inc. | Year:                         | 2019             | Make of<br>Chassis: | Freightliner | Year:             | 2021        |
| Bus Type:                      | С                           |                               |                  | Mileage:            | 11547        |                   |             |
| Inspection<br>Status:          | Α                           |                               | Inspected<br>By: | Joel Flores         |              | PE:               | 7415        |

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.