

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|------------------------------|------------------------|------------|-------------------------|--------------|
| Type of Inspection: | Semi-Annual | Date: | 8/5/2021 | Time: | 9:13 AM |
| Name of School Corporation: | NORTH LAWRENCE COMM. SCHOOLS | Corp ID: | 475075 | | |
| Address of School Corporation: | 595 Stars Blvd | | | | |
| City: | Bedford | Zip: | 47421 | County Number: | 47 |
| VIN: | 4UZABRDC18CZ10883 | License Number: | nlcsa15 | Bus Number: | A59 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2007 | Make of Chassis: | Freightliner |
| Bus Type: | A1 | Mileage: | 145089 | | |
| Inspection Status: | O | Inspected By: | Mike Adams | PE: | 7407 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 13-1-1 | Any clearance light is missing, cracked, faded, wrong color, or inoperative |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.