

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 8/5/2021	<b>Time:</b> 10:29 AM
<b>Name of School Corporation:</b> NORTHERN RUSH COUNTY SCHOOLS INC	<b>Corp ID:</b> 9955	
<b>Address of School Corporation:</b> 929 E South Street		
<b>City:</b> MAYS	<b>Zip:</b> 46155	<b>County Number:</b> 70
<b>VIN:</b> 4DRBRAAN13A947251	<b>License Number:</b> B389L	<b>Bus Number:</b> 7
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2002	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2002		
<b>Bus Type:</b> C	<b>Mileage:</b> 164010	
<b>Inspection Status:</b> R	<b>Inspected By:</b> Jeremy Mason	<b>PE:</b> 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
43-1-8	Any required lettering is missing or faded.
68-1-1	Washers do not function properly in any manner
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
57-1-5	Step-well light is missing or inoperative

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.