## REPORT OF SCHOOL BUS INSPECTION

Type of 9:51 Time: Annual Date: 8/9/2021 Inspection: AM Name of School Corporation: NORTH WEST HENDRICKS SCHOOLS Corp ID: 323295 **Address of School Corporation:** PO Box 70 County City: Lizton Zip: 46149 32 Number: License VIN: 4UZABRFD6KCKY5507 B941P **Bus Number:** 15 Number: Make of Thomas Built Buses, Year: 2018 Freightliner Year: Make of Body: 2018 Inc. Chassis: **Bus Type:** С Mileage: 21720 Inspected PE: **Inspection Status:** O Jeff Stone 8184 By:

## Violations - Rejected

Inspection Code Description

There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver

## **Violations - Out of Service**

<u>Inspection Code</u> <u>Description</u>

8-2-8 The electric power assist motor fails to operate

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.